

F-4000 FRAME SIZE				
Model Number	Rockwell P/N	Elwood P/N	List Price	Rebuild Price
F-4030-Q-H00AA	193488	999-001-0390	\$3,889.20	\$2,333.52
FSM430	401-34318-01	999-001-0390	\$3,889.01	\$2,333.41
F-4030-Q-H00AN	193489	999-001-0392	\$3,889.01	\$2,333.41
FSM430 56C	401-34393-00	999-001-0392	\$3,889.01	\$2,333.41
F-4030-Q-H04AA	193490	999-001-0391	\$4,774.94	\$2,864.97
FSM430 B24	401-34318-20	999-001-0391	\$4,776.32	\$2,865.79
F-4030-Q-H04AN	193491	999-001-0393	\$4,776.32	\$2,865.79
FSM430 56C B24	401-34318-26	999-001-0393	\$4,776.32	\$2,865.79
F-4030-Q-K00AA	195853	999-001-0409	\$4,157.27	\$2,494.36
F-4030-Q-K00AN	195858	999-001-0413	\$4,157.27	\$2,494.36
F-4030-Q-K04AA	195857	999-001-0412	\$5,043.20	\$3,025.92
F-4030-Q-K04AN	195859	999-001-0414	\$5,043.20	\$3,025.92
F-4050-Q-H00AA	193493	999-001-0394	\$4,600.23	\$2,760.14
FSM460	401-34320-01	999-001-0394	\$4,600.23	\$2,760.14
F-4050-Q-H00AN	193494	999-001-0395	\$4,600.23	\$2,760.14
FSM460 56C	401-34320-06	999-001-0395	\$4,600.23	\$2,760.14
F-4050-Q-H01AN	195880	999-001-0426	\$6,691.25	\$4,014.75
F-4050-Q-H04AA	193495	999-001-0396	\$6,193.26	\$3,715.95
FSM460 B24	401-34320-20	999-001-0396	\$6,193.26	\$3,715.95
F-4050-Q-H04AN	193496	999-001-0397	\$6,193.26	\$3,715.95
F-4050-Q-K00AA	195860	999-001-0415	\$4,689.65	\$2,813.79
FSM460 E5000	401-34320-50	999-001-0415	\$4,689.65	\$2,813.79
F-4050-Q-K00AN	195862	999-001-0417	\$4,689.65	\$2,813.79
F-4050-Q-K04AA	195861	999-001-0416	\$6,281.30	\$3,768.78
F-4050-Q-K04AN	195863	999-001-0418	\$6,281.30	\$3,768.78
F-4075-R-H00AA	193497	999-001-0398	\$5,220.66	\$3,132.40
FSM490	401-34322-01	999-001-0398	\$5,220.66	\$3,132.40
F-4075-R-H00AN	193498	999-001-0399	\$5,220.66	\$3,132.40
F-4075-R-H01AA	401-34323-01	999-001-0427	\$7,486.39	\$4,491.83
F-4075-R-H04AA	193499	999-001-0400	\$6,815.06	\$4,089.04
FSM490 B24	401-34322-20	999-001-0400	\$6,815.06	\$4,089.04
F-4075-R-H01AN		999-001-0389	\$7,486.39	\$2,267.00
F-4075-R-H04AN	193500	999-001-0401	\$6,815.06	\$4,089.04
F-4075-R-K00AA	195852	999-001-0408	\$5,486.16	\$3,291.70
F-4075-R-K00AN	193856	999-001-0411	\$5,486.16	\$3,291.70
F-4075-R-K04AA	195864	999-001-0419	\$6,991.14	\$4,194.69
F-4075-R-K04AN	195865	999-001-0420	\$6,991.14	\$4,194.69

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment



Elwood Corporation
High Performance Motors
2701 N. Green Bay Rd.
Racine, WI 53404
January 1, 2026

s://www.elwood.com/motors/fseries/F-Series.html

F-6000 FRAME SIZE				
Model Number	Rockwell P/N	Elwood P/N	List Price	Rebuild Price
F-6100-R-H00AA	193501	999-001-0402	\$6,136.52	\$3,681.91
FSM610	401-34324-01	999-001-0402	\$6,136.52	\$3,681.91
F-6100-R-H04AA	193502	999-001-0403	\$8,118.81	\$4,871.29
F-6100-R-K00AA	193855	999-001-0410	\$6,513.57	\$3,908.14
F-6100-R-K04AA	195866	999-001-0421	\$8,299.62	\$4,979.77
F-6200-R-H00AA	193503	999-001-0404	\$8,050.46	\$4,830.27
FSM620	401-34326-01	999-001-0404	\$8,050.46	\$4,830.27
F-6200-R-H04AA	193504	999-001-0405	\$9,741.69	\$5,845.01
F-6200-R-K00AA	195867	999-001-0422	\$8,426.41	\$5,055.84
F-6200-R-K04AA	195868	999-001-0423	\$9,985.34	\$5,991.21
F-6300-R-H00AA	193505	999-001-0406	\$10,509.03	\$6,305.42
FSM630	401-34328-01	999-001-0406	\$10,509.03	\$6,305.42
F-6300-R-H04AA	193506	999-001-0407	\$12,201.37	\$7,320.82
F-6300-R-K00AA	195869	999-001-0424	\$10,886.09	\$6,531.65
F-6300-R-K04AA	195870	999-001-0425	\$12,388.79	\$7,433.28

Updated weekly and subject to change. Call to confirm.
Consult factory for model numbers not listed.
Built with original design, documentation, and equipment